

ADDENDUM No. 3 – (March 25, 2019)

ADDENDUM TO: **Underground Drainage Vault Repair, RJS**
BID NUMBER: **Bid #18-10**
BID DUE DATE: **Thursday, March 28, 2019 not later than 10:00am**

TO BIDDER: This addendum is an integral part of the Bid file under consideration by you as a bidder in connection with the subject matter identified above. For the purpose of clarification, the following additions, changes, modifications and replacements noted below have been made to the Bid and have been made to the Bid file which bears the above title.

Bids submitted shall conform to these additions and modifications noted herein and including all issued addendums.

Review Attachment(s)

Note: To qualify your proposal, of which this addendum becomes a part, this form must be completed and returned to this office with the proposal.

Date: _____

Authorized Signature of Company Rep.

Printed Name of Company Rep.

Company: _____

Address: _____

Telephone: _____

Contact's Email: _____

End of Addendum #3

**ADDENDUM THREE to Bid #18-10
March 25, 2019**

**Underground Drainage Vault Repair
Raymond James Stadium**

The following additional questions were received. The responses in green font shall be incorporated into the Bid Documents:

Additional questions:-

1. Is the requirement for Builder's Risk insurance for this project a mistake? **Builder's Risk is not required**

2. What permits has the Authority acquired for the envisioned work and what permits will Cloud 9 Services, Inc. be required to acquire? **No permits are needed as this is maintenance & repair work.**

3. What is the vault letter designation of the vault requiring the wall repairs? **Vault L in the attached plan, to the right of note 41.**

4. The two joints that are offset and the spigot are missing/broken We don't think grout alone will fix these two joints and a structural cipp repair should be done. I see addendum two says they should be priced as a voluntary alternative, I can't give a warranty on grouting these two joints unless we install cipp liners on these two joints. **CIPP liners should be installed in order to provide a warranty. Provide a price difference for doing this versus just an injection grout repair per the alternate on the bid form.**

END OF ADDENDUM


BID FORM

Project: RAYMOND JAMES STADIUM
Underground Drainage Vault Repair
Bid #18-10
TAMPA SPORTS AUTHORITY


The undersigned has attended the mandatory pre bid meeting, examined all Contract Documents, and the site for the above project and agrees to furnish and pay for all labor, materials, equipment, plant, appurtances, services, taxes unless declared exempt by the Contract Documents and utilities required to complete this project according to all the requirements of the Contract Documents, including all addenda, at and for the price(s) stated below regardless of any increase in wages or material prices.

The Contractor in submitting this bid guarantees the following price for forty-five (45) days:

BASE PROJECT BID:	
<hr/>	Dollars
Total Price in words	\$ <hr/>
	Price in Figures
Voluntary Bid Alternate #1 (Cured in place point repairs in addition to injection grouting)	
<hr/>	Dollars
Total Price in words	\$ <hr/>
	Price in Figures



MATCH LINE "C" SEE SHEET 5



FLORIDA DESIGN CONSULTANTS, INC.
 ENGINEERS, ENVIRONMENTALISTS, SURVEYORS & PLANNERS
 4000 WEST WINDYBROOK DRIVE, SUITE 100
 TAMPA, FLORIDA 33613
 Telephone: 813-972-4222
 Certificate of Authorization LD 6707
 State of Florida

METREX OF CENTRAL FLORIDA, INC.

RECORD SURVEY
 DRAINAGE STRUCTURES
 TAMPA NFL STADIUM