Schedule 1 - Equipment List

TAMPA SPORTS AUTHORITY MAINTENANCE SCHEDULE											
Number	Area	Manufactuer	Special Notes								
1	COOLING TOWER # 1 / 1070 Tons	The Cooling Tower Company	Tower replaced and installed 8/1/2011								
2	COOLING TOWER # 2 / 1070 Tons	The Cooling Tower Company	Tower replaced and installed 8/1/2011								
3	ANNUAL OIL ANALYSIS COOLING TOWER # 1										
4	ANNUAL OIL ANALYSIS COOLING TOWER # 2										
5	CHILLER # 1 / 1500 Tons Mag - dual compressor	Daikin	New - 6/1/2017, 1 year full maintenance / 5 year full labor & repair warranty								
6	CHILLER # 2 / 970 Tons Centrifugal	Daikin	Overhauled - 6/1/2017 / 1 year full labor & repair warranty								
7	STARTERS CHILLER # 1 / 1500 Tons	Daikin	New - 6/1/2017, 1 year full maintenance / 5 year full labor & repair warranty								
8	STARTER CHILLER # 2 / 970 Tons		Existing 1998								
9	ANNUAL OIL ANALYSIS CHILLER # 1		Does Not Apply								
10	ANNUAL OIL ANALYSIS CHILLER # 2										
11	WATER TREATMENT CONDENSER LOOP	NALCO	Based on Towers 1 &2 and Chillers 1 & 2. Services provided by NALCO through 6/1/2018.								
12	WATER TREATMENT CLOSED CHILLED LOOP	NALCO	Single chilled water building loop with single pot feeder. Services provided by NALCO through 6/1/2018.								
13	PRIMARY CHW PUMP # 1 / 40 H.P	Armstrong	Existing 1998								
14	PRIMARY CHW PUMP # 2 / 40 H.P	Armstrong	Existing 1998								
15	PRIMARY CHW PUMP # 3 / 40 H.P	Armstrong	Existing 1998								
16	SECONDARY CHWP # 1 / 75 H.P	Armstrong	Existing 1998								
17	SECONDARY CHWP # 2 / 75 H.P	Armstrong	Existing 1998								
18	SECONDARY CHWP # 3 / 75 H.P	Armstrong	Existing 1998								
19	SECONDARY CHWP # 4 / 75 H.P	Bell & Gossett	Redundant pump installed 8/1/2011								
20	CONDENSER WATER PUMP # 1 / 150 H.P	TACO	New - 6/1/2017 1 year full labor and repair warranty / 5 year Motor & Pump warranty								
21	CONDENSER WATER PUMP # 2 / 150 H.P	TACO	New - 6/1/2017 1 year full labor and repair warranty / 5 year Motor & Pump warranty								
22	CONDENSER WATER PUMP # 5 / 5 H.P	Armstrong	Existing 1998								
23	COOLING TOWER # 3 / 1000 Tons	The Cooling Tower Company	NEW 6/1/2017, 1 year full labor and repair warranty / 5 year gear box & Motor warranty								
	ANNUAL OIL ANALYSIS COOLING TOWER # 3	and coming torrest company									
	CHILLER # 3 / 350 Tons Centrifugal	Daikin	Existing 2000								
	STARTER CHILLER # 3 / 350 Tons		Existing 2000								
27	ANNUAL OIL ANALYSIS CHILLER # 3										
28	WATER TREATMENT	NALCO	Based on Tower 3 and Chiller 3 Services provided by NALCO through 6/1/2018.								
29	PRIMARY CHW PUMP # 4 / 40 H.P	TACO	New - 6/1/2017 1 year full labor and repair warranty / 5 year Motor & Pump warranty								
30	SECONDARY PUMP # 5 / 75 H.P	TACO	New - 6/1/2017 1 year full labor and repair warranty / 5 year Motor & Pump warranty								
31	CONDENSER WATER PUMP # 3 / 150 H.P	TACO	New - 6/1/2017 1 year full labor and repair warranty / 5 year Motor & Pump warranty								
32	CONDENSER WATER PUMP # 4 / 150 H.P	TACO	New - 6/1/2017 1 year full labor and repair warranty / 5 year Motor & Pump warranty								

Schedule 2 - Maintenance Schedule

TAMPA SPORTS AUTHORITY MAINTENANCE SCHEDULE													
Number	Area	FEB	MAR	APR	MAY	JUNE	JULY	AUG	SEP	ОСТ	NOV	DEC	JAN
1	COOLING TOWER # 1 / 1070 Tons	0			Α			0			0		
2	COOLING TOWER # 2 / 1070 Tons	0			Α			0			0		
3	ANNUAL OIL ANALYSIS COOLING TOWER # 1									Α			
4	ANNUAL OIL ANALYSIS COOLING TOWER # 2									Α			
5	CHILLER # 1 / 1500 Tons Mag - dual compressor			Α			0			0			0
6	CHILLER # 2 / 970 Tons			Α			0			0			0
7	STARTERS CHILLER # 1 / 1500 Tons			Α			0			0			0
8	STARTER CHILLER # 2 / 970 Tons			Α			0			0			0
9	ANNUAL OIL ANALYSIS CHILLER # 1		Does Not Apply										
10	ANNUAL OIL ANALYSIS CHILLER TOWER # 2			Х									
11	WATER TREATMENT CONDENSER LOOP	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х
12	WATER TREATMENT CLOSED CHILLED LOOP	Х	Х	X	Х	Х	Х	X	Х	X	Х	X	Х
13	PRIMARY CHW PUMP # 1 / 40 H.P	0					Α			0			0
14	PRIMARY CHW PUMP # 2 / 40 H.P	0					Α			0			0
15	PRIMARY CHW PUMP # 3 / 40 H.P	0					Α			0			0
16	SECONDARY CHWP # 1 / 75 H.P	0					Α			0			0
17	SECONDARY CHWP # 2 / 75 H.P	0					Α			0			0
18	SECONDARY CHWP # 3 / 75 H.P	0					Α			0			0
19	SECONDARY CHWP # 4 / 75 H.P	0					Α			0			0
20	CONDENSER WATER PUMP # 1 / 150 H.P	0					Α			0			0
21	CONDENSER WATER PUMP # 2 / 150 H.P	0					Α			0			0
22	CONDENSER WATER PUMP # 5 /	0					Α			0			0
23	COOLING TOWER # 3 / 1500 Tons	0			Α			0			0		
24	ANNUAL OIL ANALYSIS COOLING TOWER #3				Х								
25	CHILLER # 3 / 350 Tons		Α				0		0			0	
26	STARTER CHILLER # 3 / 350 Tons		Α				0		0			0	
27	ANNUAL OIL ANALYSIS CHILLER # 3		Х										
28	WATER TREATMENT	X	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х	Х
29	PRIMARY CHW PUMP # 4 / 40 H.P	0					Α			0			0
30	SECONDARY PUMP # 5 / 75 H.P	0					Α			0			0
31	CONDENSER WATER PUMP # 3 / 150 H.P	0					Α			0			0
32	CONDENSER WATER PUMP # 4 / 150 H.P	0					Α			0			0

Note: "A" represents Annual Maintenance. Annual Maintenance shall be performed as per manufacturer's recommendations and industry standards.

Note: "O" represents Operational Inspection. Operational Inspection shall be performed as per manufacturer's recommendations and industry standards.

Note: "X" Represents listed item is to be performed in the month identified.